

## 3 PHASE DIGITAL POWER CLAMP METER



### ***Safety Precautions***

- Read these operation instructions thoroughly and completely before operating your meter. Pay particular attention to WARNING. The instructions in these warnings must be followed.
- You must be careful when working with voltages above 30V AC. Keep fingers behind the probe barriers while measuring.
- Never use the meter to measure voltages that might exceed the maximum allowable input value of any function measurement mode.
- Always inspect your meter and test leads before every use. If any abnormal conditions exist: broken test leads, cracked cases, LCD not reading, etc, do not attempt to take any measurement.
- Using the meter with the equipped test leads is only conform to safety requirements. If you need instead broken test leads, you must replaced with the same as type and electric specification.
- Never touch a voltage source when the test leads are plugged into a current jack.
- Do not expose the instrument to direct sunlight, extreme temperature or moisture.






**WARNING**

***READ THE INSTRUCTIONS BEFORE  
USING THE INSTRUMENT***

## ***Safety Information***

Three-phase digital power clamp meter has been designed according to IEC1010-1 and IEC1010-2-032 concerning safety requirements for electrical measuring instruments and handheld clamps with pollution degree 2, overvoltage category ( 600V CATIII).

## ***Safety Symbols***



-  Important safety information, refer to the operating manual
-  Dangerous voltage may be present.
-  Earth ground
-  Double insulation (Protection class II )
-  Battery

## ***General Description***

Three-phase digital power clamp meter is a handheld aptitude meter with power measurement, it is incorporated current meter and power measurement instrument. The meter is composed of three channels: voltage, current, power and single chip Microcontroller. It has powerful measuring and data processing software, and complete to measure, calculate and display of the 8 parameters: Voltage, Current, Active Power, Power Factor, Apparent Power, Reactive Power, Active Energy, Frequency. It has Stable capability, easy operation. It is especially suitable for measurement and overhaul of the electric power equipment and the power-supply circuit on the spot. The structure of the instrument is pincers, it is very small, very light and portable, make measurement easy and fast. To the power measurement user, the digital power clamp meter which is used completely in three-phase system is one of the best instrument.

## ***Feature***

1. For power measurement of 3-phase 3-wire circuit, 3-phase 4-wire circuit, single-phase circuit.
2. The instrument can complete the true RMS value measurement. If there is nonsinusoidal AC current input signal, it can accurately measure the active current.
3. Using autorange switch circuit and modulus transducer which has 8000 count and high resolution, the instrument has high accuracy and easy operation.
4. Minimum current of Active Energy measurement is 0.5A, it can measure expending energy per hour of general electrical equipment.  
Measurement and display five parameters of power: Active Power, Apparent Power, Power Factor, Reactive Power, Active Energy.
5. Double display two parameters on each menu and store 28 groups of measurement parameter.
6. Measure five power parameters of each phase and total power value in three-phase measurement mode respectively.
7. Multifunctional button control, there are double scales analogue bar



V1: The input terminal for the first phase, using the yellow test lead to connect.

V2: The input terminal for the second phase, using the green test lead to connect.

V3: The input terminal for the third phase, using the red test lead to connect.

COM: Common terminal, the earth input terminal for all measurement modes, using the black test lead to connect.

6. LCD Display

4 digits display, 7 segment LCD to display function mode, measured value and symbols.

7. Trigger

Press the lever to open the transformer. When the lever is released, the jaws will close again.

8. RS232C Data Interface

Your clamp meter can use a serial interface cable to communicate with a computer. Refer to Figure 18 for complete instructions.

**Using the Selector**

Turn the meter on by rotating the selector to any function as following . ( **Table 1. Introducing The Selector** )


ITEM	DESCRIPTION
OFF	<b>POWER OFF.</b> Turn the meter off
EX-Ⓟ	<b>EXTERNAL POWER SUPPLY.</b> No use battery, select tested voltage signal be power supply for Active Energy measurement for long at one time.
MR	<b>RECALL DATA.</b> Recall saved data in the meter memory.
ΣW	<b>TOTAL POWER.</b> For display total power value of three phase

( **Table 1. Introducing The Selector** )

ITEM	DESCRIPTION
Φ3	<b>THIRD MEASUREMENT CHANNEL.</b> For V3 input terminal measurement
Φ2	<b>SECOND MEASUREMENT CHANNEL.</b> For V2 input terminal measurement
Φ1	<b>FIRST MEASUREMENT CHANNEL.</b> For V1 input terminal measurement

**Using the buttons**

( **Table 2. Function Button** )

ITEM	DESCRIPTION
	Active Power, Power Factor Measurement Button.



	Data Transmit Button
	Clear Memory Button
	Backlight Button
	Maximum Value Button/ Previous Record Button
	Minimum Value Button/ Next Record Button
	Data Save Button



Active Power, Power Factor Measurement Button



button to measure Active Power and Power Factor in measurement mode. Then the LCD shows Active Power reading in the primary display and Power Factor reading in the secondary display.



Apparent power, Reactive Power measurement button



button to measure Apparent Power and Reactive Power in measurement mode. Then the LCD shows Apparent Power reading in the primary display and Reactive Power reading in the secondary display.




Active Energy, Time Measurement Button




CD shows




je in the

 Current Measurement Button


 button to measure current of the circuit and display

the measurement value in the LCD display.


 Data Transmit Button


 button to transmit measured data to a computer by

special interface cable, you can record current measured value and print reports and data trend curve drawing.


Before  button to transmittal measured data, you


must connect RS232C interface cable to the clamp meter and a computer, the communication function is working.

 Clear Memory Button


 button for three seconds to erase all measured data

in the meter memory in the measurement mode.

 Backlight Button

 button to turn the backlight on or off. When the back-

-light turned on over five seconds, it will turn off automatically.

 Maximum Value Measurement Button / Previous Record

Button


 button to measure maximum value in measurement

mode. The display shows current maximum value in the secondary display.

When you turn the selector to  button to recall

previous memory location and display the data on the LCD. Once pressing this button, the clamp meter recalls a memory location

previous current location.

 Minimum Value Measurement Button / Next Record Button

 button to measure minimum value in measurement

mode, the display shows current minimum value in the secondary display.


- 8 -

When you turn the selector to  button to recall


next memory location and display the data on the LCD. Once

pressing this button, the clamp meter recalls a memory location next current location.

 Data Save Button




 button to save current measured data to the meter in

measured mode. The meter can save 28 groups of measured data into the meter at most.







( For primary display )


10. Active power unit (kW)、 Active Energy unit (kWh)
11. 4 digit display ( For primary display )
12. Frequency unit
13. Voltage unit (V), current unit (A), Apparent Power unit (kVA),  
Reactive Power unit (kVAr) ( For secondary display )
14. Time unit : hour(h)、 minute(min)
15. Overflow symbol
16. 100 graduate scale
17. 40 graduate scale
18. Bar graph
19. 4 digit display ( For secondary display )
20. Frequency unit
21. Time symbol
22. Negative sign of scale
23. Number of memory location symbol
24. Recall data symbol
25. Save data symbol





















**NOTE:** When you turn the selector to EX- $\text{P}$  to measure voltage or power parameter, the












✦



✦

✦




Connect RS232C interface cable to the clamp meter as shown in Figure 18, then rotate the interface cable deasil to lock it in the meter. Connect the other plug of the interface cable to a serial port of a computer. Then the meter can transmit measured data to computer by the infrared photoelectricity RS232C interface in real-time mode. If you want to take out the interface cable from the meter, first you must rotate the cable widdershins to unlock it, then you can pull out it .


You will install the special data record software into the computer according to README.TEXT file in SETUP disk. When the meter is in measurement mo  button, you can record and

print the measured data of the meter in real time mode in the WINDOWS. The software can



★ **Wave Diagram of Power** (PE KW) :





300V	$\pm(1.2\%+5)$	0.1V	(10Pf SHUNT)
600V	$\pm(1.2\%+5)$	0.1V	

Max. Overload Voltage: 750V (RMS)

**AC CURRENT****RMS**

RANGE	ACCURACY	RESOLUTION
40A	±(2%+5)	0.1A
100A	±(2%+5)	0.1A
400A	±(2%+5)	0.1A
1000A	±(2%+5)	0.1A

Max. Overload Current: 1500A

**ACTIVE POWER****(W)**

RANGE	ACCURACY	RESOLUTION
4kW	±(3%+5)	0.01kW
10kW	±(3%+5)	0.01kW
40kW	±(3%+5)	0.01kW
100kW	±(3%+5)	0.01kW
600kW	±(3%+5)	0.1kW

Minimum measurement current : 5A

Minimum measurement voltage : 20V

**APPARENT POWER****(VA)**

RANGE	ACCURACY	RESOLUTION
4kVA	±(3%+5)	0.01kVA
10kVA	±(3%+5)	0.01kVA
40kVA	±(3%+5)	0.01kVA
100kVA	±(3%+5)	0.01kVA
600kVA	±(3%+5)	0.1kVA

Minimum measurement current : 5A

Minimum measurement voltage : 20V

**POWER FACTOR****(PF)**

RANGE	ACCURACY	RESOLUTION
0.3~1 Capacitive	±(0.02+2)	0.001
0.3~1 Inductive	±(0.02+2)	0.001

Minimum measurement current : 5A

Minimum measurement voltage : 20V

**REACTIVE POWER**

$$(\text{Var})^2 = (\text{VA})^2 - \text{W}^2$$

RANGE	ACCURACY	RESOLUTION
4kVAr	±(4%+5)	0.01kVAr
10kVAr	±(4%+5)	0.01kVAr
40kVAr	±(4%+5)	0.01kVAr
100kVAr	±(4%+5)	0.01kVAr
600kVAr	±(4%+5)	0.1kVAr

Minimum input current : 5A

Minimum input voltage : 20V

Recording Voltage value、current value、Active Power value to calculate Reactive Power value,  
The calculating accuracy is 0.01% of the range.

#### **ACTIVE ENERGY (kWh)**

RANGE	ACCURACY	RESOLUTION
1~9999kWh	±(3%+2)	0.001kWh

Minimum measurement current : 0.5A

Minimum measurement voltage : 10V

#### **FREQUENCY ( Hz )**

RANGE	ACCURACY	RESOLUTION
20Hz~1kHz	0.5%	0.1Hz

Minimum measurement voltage: 20V

\* Accuracy: % of reading + number of digits

The specification given assume an operating temperature: 18 °C ~ 28 °C ,humidity up to:


80% , the frequency of voltage and current is 45Hz~65Hz

\* Maximum common made voltage: 600V AC RMS

\* Display : LCD 9999

\* Range : autorange

\* Overrange indication: Figure "OL" on the display

\* Reading Holding: Figure  n the display

\* Power supply : 4× 1.5V AA

\* Power consume: 250mW

\* Storage temperature: -20°C~70°C

\* Operating temperature: 0°C~40°C

\* Dimension size: 300mm×103mm×51mm

\* Weight: approx. 500g ( include battery )

## **ACCESSORIES**

Battery	1.5V AA	4
Test Leads	(MS3000)	1
Connect test clamp	(MS3102)	1
RS232C interface cable ( MS3403 )		1
PC Data Record graph software		1
Carry Case		1